

Grooved-type Photoelectric Sensor

E3Z-G

- Grooved design eliminates the need for optical axis adjustment.
- Two-axis models also available.
- Ideal for detection and positioning for cranes and conveyor systems in automated warehouses.



Ordering Information

Sensor Unit

Appearance	ance Connection method Sensing distance		Number of	Model	
			optical axes	NPN output	PNP output
	Pre-wired (0.5/2 m)		1	E3Z-G61	E3Z-G81
beam	Junction connector	05 707		E3Z-G61-M3J	E3Z-G81-M3J
	Pre-wired (0.5/2 m)	25 ()	2	E3Z-G62	E3Z-G82
	Junction connector			E3Z-G62-M3J	E3Z-G82-M3J
	Appearance	Pre-wired (0.5/2 m) Junction connector Pre-wired (0.5/2 m)	Pre-wired (0.5/2 m) Junction connector Pre-wired (0.5/2 m) 25 mm	Pre-wired (0.5/2 m) Junction connector Pre-wired (0.5/2 m) 25 mm 2 225 mm	Pre-wired (0.5/2 m) Junction connector Pre-wired (0.5/2 m) 25 mm 2 E3Z-G61 E3Z-G61-M3J 2 E3Z-G62

Note: Models with a 0.5-m cable are available. When ordering, specify the cable length by adding the code "0.5M" to the model number (e.g., E3Z-G61 0.5M).

■ Accessories (Order Separately)

Sensor I/O Connector

Cable specifications	Арр	earance	Type of cable		Model
Standard cable	Otro i subst		2 m	Four-core cable	XS3F-M421-402-A
	Straight	5 m		XS3F-M421-405-A	
	L-shape		2 m		XS3F-M422-402-A
	2 5.1.4.75		5 m		XS3F-M422-405-A

Specifications

■ Ratings/Characteristics


	Sensing method	Through beam (grooved type)				
Numl	per of optical axes	1		2		
	NPN output	E3Z-G61	E3Z-G61-M3J	E3Z-G62	E3Z-G62-M3J	
Item	PNP output	E3Z-G81	E3Z-G81-M3J	E3Z-G82	E3Z-G82-M3J	
Sensing distance		25 mm (distance between arms of groove)				
Light source (wave I	ength)	Infrared LED (940 nm)				
Power supply voltag	е	12 to 24 VDC±10% including 10% (p-p) max. ripple				
Current consumption	n	25 mA max. 40 mA max.				
Control output		Load power supply voltage: 26.4 VDC max. Load current: 100 mA max. (Residual voltage: 1 V max.) L-ON/D-ON selectable (With 2-axis models, L-ON or D-ON can be selected for each axis.)				
Circuit protection		Protection from reversed power supply connection, output short-circuits, and mutual interference.				
Response time		Operation or reset: 1 ms max.				



Sensing method	Through beam (grooved type)				
Number of optical axes	1		2		
NPN output	E3Z-G61 E3Z-G61-M3J		E3Z-G62	E3Z-G62-M3J	
Item PNP output	E3Z-G81	E3Z-G81-M3J	E3Z-G82	E3Z-G82-M3J	
Ambient illumination (receiver side)	Incandescent lamp: 3,000 lux max. Sunlight: 10,000 lux max.				
Ambient temperature	Operating: -25 to 55°C/Storage: -40 to 70°C (with no icing or condensation)				
Ambient humidity	Operating: 35% to 85%/Storage: 35% to 95% (with no condensation)				
Insulation resistance	20 MΩmin. at 500 VDC between lead wires and case				
Dielectric strength	1,000 VAC, 50/60 Hz for 1 min between lead wires and case				
Vibration resistance (destruction)	10 to 55 Hz, 1.5-mm double amplitude for 2 hours each in X, Y, and Z directions				
Shock resistance (destruction)	500 m/s ² 3 times each in X, Y, and Z directions				
Enclosure rating	IP64 (IEC60529)				
Connection method	Pre-wired cable (length: 2 m or 0.5 m)	Junction connector	Pre-wired cable (length: 2 m or 0.5 m)	Junction connector	
Indicator	Operation indicator (orange)				
Weight (packed state)	Pre-wired models (with 2-m cable): 65 g Models with junction connectors: 30 g				
Material	ABS				
Accessories	Instruction sheet				

Operation


■ Output Circuits (NPN Output)



■ Output Circuits (PNP Output)

No. of optical axes/model	Out- put tran- sistor status	Timing chart	Mode selector	Output circuit
1 axis E3Z-G81 E3Z-G81- M3J	Light ON	Incident Interrupted Operation ON Indicator (orange) OFF OUtput ON Itansistor OFF Load Operate (relay) Reset (Between brown and black	LIGHT ON (L/ON)	Operation indicator (Control output) Black (S1) 100 mA max (relay) 0 V
	Dark ON	Incident Interrupted Operation ON indicator (orange) OFF ON Urbut ON Urbanistic OFF Load Operate (relay) Reset (Between brown and black	DARK ON (D/ON)	Connector Pin Arrangement (2) (3) (7) (3) Note: Pin 2 is not used.
2 axes E3Z-G82 E3Z-G82- M3J	Light ON	Incident Interrupted Operation ON indicator (orange) OFF OUtput ON transistor OFF Icad Operate (relay) Reset (Between brown and black	LIGHT ON (L/ON)	Operation Circuit Output) Operation Selection (Control output) Main Circuit (Control output) White (S2)
	Dark ON	Incident Interrupted Operation ON Indicator (orange) OFF Output ON Itransistor OFF Load Operate (relay) Reset (Between brown and black	DARK ON (D/ON)	Zo 100 mA Load (relay) 100 mA (relay) 100 mA (relay) 0 V Connector Pin Arrangement


Structure of Sensor I/O Connector



Classification	Wire color	Connector	Use		
		pin number	1-axis models	2-axis models	
DC	Brown	1	Power supply (+V)		
	White	2		Output 2 (S2)	
	Blue	3	Power supply (0 V)		
	Black	4	Output	Output 1 (S1)	

Note: Pin 2 of 1-axis models is not used.

Dimensions





ALL DIMENSIONS SHOWN ARE IN MILLIMETERS.

To convert millimeters into inches, multiply by 0.03937. To convert grams into ounces, multiply by 0.03527.

Cat. No. E320-E1-1 In the interest of product improvement, specifications are subject to change without notice.

OMRON Corporation

Industrial Automation Company

Industrial Sensors Division Sensing Devices and Components Division H.Q. Shiokoji Horikawa, Shimogyo-ku Kyoto, 600-8530 Japan Tel: (81)75-344-7068/Fax: (81)75-344-7107

Printed in Japan 0501-1M (A)